


217 North Rocks Road North Rocks NSW 2151 Telephone 02 9683 1899 Fax 02 9630 2860

Email builder@cofair.com.au Website www.colefair.com.au



Following the successful completion of previous joinery works at the Australian Club, C&F's own Joinery Shop was engaged for the major refurbishment of Level 2 function & dining areas, including the Cedar Room and the Macleay Function Room. Panelled doors & walls were fabricated and French polished, ceilings modified for upgraded lighting, sprinklers & air conditioning. The Men's washroom was stripped out and refitted. The Club remained fully functioning at all times.

THE AUSTRALIAN CLUB – REFURBISHMENT

JOINERY

LOCATION The Australian Club Macquarie Street Sydney

YEAR 2003

BUDGET \$360,000

ARCHITECT Gordon G Fuller & Associates (Gordon Fuller Ph: 9487 4033)

CLIENT The Australian Club (Hugh Stowell Ph: 9229 0400)