



Before



Before



Before



SCEGGS Darlinghurst contacted Coleman & Fairburn with a problem: part of the timber verandah of the 1833 'Barham' building (on the National Estate Register) was badly rotted and needed replacing. Compounding the problem, the rotted corner post supported an enclosed verandah at the 2nd floor level housing computer classes. With careful planning, Coleman & Fairburn replaced the rotted structural timbers in the first bay of the verandah during a 3-week school holiday period. Timbers were replaced like-with-like and Coleman & Fairburn's own Joinery Shop matched the original profiles where necessary. Trishore Props and a steel beam supported the 2nd Floor classroom while the corner post was replaced.



After



After



During

REPAIRS TO HERITAGE VERANDAH

COMMUNITY

LOCATION	215 Forbes St, Darlinghurst	YEAR	2009	BUDGET	\$30,000
ENGINEER	Hughes Trueman P/L (Amir Bagheri Ph. 9439 2633)				
CLIENT	SCEGGS Darlinghurst School (Mick Vidovic Ph. 9332 1133)				